




208





F16.49






FI6. 5






FI6.7



FI6.8



FI6.9




Figure 10: Effect of number of reorder buffer entries on clock rate for the three sequencers